# Navajo Abandoned Uranium Mine

# **Site Screen Report**

This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits, pits and waste piles. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands that may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.

The purpose of the form is to ascertain the status and location of the identified AUM site, and record all immediate site information associated with the mine site. Decisions and recommendations on what additional steps are needed will be provided on a separate document.

# **Melvin Benally No. 3 AUM Site**

Navajo AUM Northern Region

Prepared by:

Weston Solutions, Inc.

Contract: W91238-06-F-0083

12767.063.496.1111

August 2010

Part I	Site Identification, Location and Status					
Site Names and ID numbers as applicable						
Mine ID:	435					
Map ID:	N57					
CERCLIS:	NNN000909013					
Navajo Abandoned Mine Land Reclamation Program: None						
Local name / Aliases: Benally No. 3; Benally Plot #3						
Chapter and local area: Sweetwater Chapter						
County: Apac	che	State: Arizon	a			
<b>Lat/Long:</b> 36.824946211 N / -109.265925925 W						
Nearby road and highway: Highway 160 Local Post Office: Sweetwater						
Surface Land Status: check one or more and provide ownership and contact information below						
Tribal Trust l Private Bureau of Lar State			Public lands Tribal Fee Land Allotment Fee land			
Subsurface Mineral Rights:						
No information on subsurface mineral rights ownership was found in the EPA/AUM Database.						
Claim and operator information:						
The mine site surface land status is classified as Tribal Trust Land. Historical documents showed the operator of the mine as Melvin Benally in 1955, and Byden Mines in 1955. No other historical ownership / lease information was identified in the EPA/AUM database.						
Number of residential structures within 200 feet of mine: None						

Estimated volume of mine waste onsite: None

## Part II Summary of radiological readings

#### **Highest gamma radiation measurement:**

35,533 counts per minute (cpm)

### Describe any other radiological measurements:

A total of 2,991 gamma radiation measurements were collected from the mine site, ranging from 7,199 cpm to 35,533 cpm. Measurements collected in the vicinity of possible work area were found at levels up to approximately 35,000 cpm. The measurements are represented in Figures 1 and 2.


## **Background Locations**

**Average background =** 13265 cpm

#1 13265 cpm

#### **Distribution Chart and Statistics:**

The following chart and statistics were generated by ESRI ArcGIS 9.3.1, and show the general distribution of the site gamma radiation measurements. The horizontal X axis represents the gamma radiation reading levels in cpm (lowest levels to the left). The vertical Y axis represents the frequency of each gamma radiation level.



 Count:
 2991

 Minimum:
 7199,00000

 Maximum:
 35533,00000

 Sum:
 33903800,00000

 Mean:
 11335,27248

 Median:
 11053,00000

 Standard Deviation:
 2218,61175

#### Part III Status of Reclamation and Mine Waste

The following information was obtained from the Navajo Abandoned Mine Land Reclamation Program (NAMLRP) Point Features Database:

NAMLRP Status of the mine site: Reclaimed : No Waste Pile onsite : No

**NAMLRP Project Number:** None

**NAMLRP Mine features:** 2 Prospects

The following information was obtained from field observations collected during the 2010 site screening:

Provide description and status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all caps.

of any recumulation caps. Troce contained of an eaps.					
Observed reclamation work and status:					
Adits					
None					
Waste Piles					
None					
Pits					
None					

## **Other Debris and Mine Features**

**Shafts** None

Various mining debris, metal cans, etc.

#### **Part IV**

#### **Site observations and Environs**

Observed Structures: list number of and describe human habitation status of structures at the following distances from mine:

**0 to 200 feet:** None

200 feet to 0.25 mile: None

Observed Public or commercial structure: list and describe all schools, clinics, Chapter Houses, places of business and any other structure used by members of the community at the following distances:

0 to 200 feet: None

200 feet to 0.25 mile: None

Levels measured around the perimeter(s) of the identified structure(s):

None

Observed water sources: list the number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine:

0 to 0.25 miles: None

**0.25 miles to 4 miles:** None

Sensitive environments: note and describe all sensitive environments located within visible range of the mine site, including: wetlands, endangered species, habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation.

None

Known Site History: include information from interviews with Chapter officials and residents. Note information on mine ownership, type of mining operation, period of operation, known amount of production, and any other information as provided.

Melvin Benally No. 3 mine consists of an area 23,319.67 m<sup>2</sup>. The mine was identified as being operational in 1955. Historical documents showed the operator of the mine as Melvin Benally in 1955, and Byden Mines in 1955. While operational, the mine had a total reported production volume of 66 tons. No other historical information or any additional ownership / lease information was identified in the EPA/AUM database.

## Part V Response Action Summary

**Site Name(s):** Melvin Benally No. 3 **Chapter:** Sweetwater

## **Decision Criteria**

Is there an unreclaimed waste pile at the site? No

At what distance from the waste pile is the nearest residential structure located? None

At what distances from the waste pile are there potential drinking water sources? None

Is there a reclamation cap or sealed adit in place at the site? No

Is the cap/seal functionally intact? No

Is the cap/seal sufficiently degraded to create a concern about releases? No

At what distance from the cap/seal is the nearest domestic structure located? None

At what distance from the cap/seal is the nearest domestic drinking water source? None

### **Summary of emergency response factors**

None

## **Summary hazard ranking system factors**

None

## **Summary of reclamation factors**

None

## Part VI Photos



Photo 1. Melvin Benally No. 3 site



Photo 2. Melvin Benally No. 3 site

Name:

# Part VII Contacts Reports and Information

Stanley Edison (928) 871-6861

Eugene Esplain (928) 871-7331					
Title or official role (if any) Navajo EPA Superfund Program					
AddressPO Box 2946, Window Rock, AZ 86515					
Information provided <u>Lead Regulatory Agency</u>					
Name_	_				
Title or official role (if any)					
Telephone number					
Information provided					
Name	_				
Title or official role (if any)					
Telephone number					
Information provided					
Name_	_				
Title or official role (if any)					
Telephone number					
Information provided					

Figure 1 - Gamma Radiation Measurements, Above Two Times Background
Melvin Benally No. 3 (435)
Sweetwater Chapter, Navajo Nation





Figure 2 - Gamma Radiation Measurements Melvin Benally No. 3 (435) Sweetwater Chapter, Navajo Nation



## Legend

### **Gamma Radiation Measurements**

- 0 10,000
- 10,000 15,000
- 15,000 20,000
- 20,000 50,000
- 50,000 100,000
- > 100,000

General Direction Down-Slope

Mine Claim Boundaries

Gamma survey conducted 06/2010 Measured as counts per minute (cpm)

Average background 13,265 cpm

